
From: Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFF136]
Sent: 2/1/2016 5:16:00 PM
To: Kaleb Acree [K.Acree@gaiconsultants.com]
CC: Leonard C Pope (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=LEONA5286e]; Michael A Glagola (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Mic0210]; John Klamut [J.Klamut@gaiconsultants.com]
Subject: Station Water Permit storm water inspections

Kaleb –

As we discussed this afternoon, we have a requirement to inspect three areas involved with the Ash Pond Closure project under the revised permit issued 01/14/16.

Please reference Part 1.F.18 (page 47 of 48) of the revised permit.

John Klamut will be creating a separate inspection form. Until then, please use the daily storm water inspection form that was created towards the end of last year.

The requirement is every 5 days AND no later than 48hrs after a storm event with precipitation.

The areas to inspect, as we discussed, are:

- S107 – the area around the West and East drop inlets between Possum Point Road, the gravel entrance off PP Road, and the installed gravel haul road along the toe of D Pond. This includes all the hay bales and silt fencing in this area. Looking into the drop inlet with the S107 sign, gauge the flow of water, if present, from West to East entering the box from the pipe, this is considered storm water.
- Outfall 010 – this is the end of pipe from the S107 labeled box under Possum Point Road to Quantico Creek, look for flow, if present, and any unusual conditions.
- S108 – this is the area that is considered the South of E Pond toe West towards the Beaver Pond. Inspect for standing water, if present, and record changes. Also inspect the hay bales/silt fence on the East end protecting this area.

We'll need inspections of these areas on 01/18, 01/21, 01/26, 01/29, 02/01, and 02/02 (assuming the rain event from today is over). Comment on the snow event 01/22 – 01/24 and the snow melt after.

Don't forget to record weather observations and rainfall totals for the post precipitation inspection.

When you have all this completed, bring the forms to me and I'll review them with you.

If for some reason you can't conduct an inspection, make arrangements with someone ahead of time they understand what you have been doing and what they are expected to document. One person conducting these inspection provides consistency.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)